

0005

DECENT OF

JAN 2 1 1992

DIVISION OF OIL GAS & MINING

January 16, 1992

Daron Haddock Permit Supervisor Division of Oil, Gas, and Mining 3 Triad Center, Suite 350 355 West North Temple Salt Lake City, Utah 84180-1203

Dear Mr. Haddock,

Attached is our certified report of activities for the Scofield Rockwaste Disposal site for the fourth quarter of 1991.

Thank you.

Sincerely,

Keith W. Zobell

Environmental Engineer

Skyline

KWZ:dk

Attachment



UTAH FUEL COMPANY SKYLINE MINES

PERMIT NO. ACT/007/005

I, William W. Shriver do hereby certify that:

- 1. A specialist experienced in the construction and maintanance of refuse piles under my supervision has conducted adequate inspection of the Scofield waste rock site in accordance with the approved plan and R614 rules; and
- 2. On December 3, 1991 an inspection of the Scofield waste rock site revealed the following:
 - a. The site has been maintained in accordance with the approved plan.
 - b. The site appeared sound with no sign of instability, structural weakness or other hazardous conditions.
 - c. 32 cubic yards of material were deposited at the site during the fourth quarter of 1991.
 - All known non-coal wastes have been removed from the site.
 - e. A ditch was constructed at the base of the highwall to divert any overland flow from the undisturbed area before entering the refuse area. This ditch was designed to carry the 100 year 6 hour event.
 - f. The site was crowned to aid in the drainage to keep water from infiltrating the disposal area.



W Shiws 1-15-92
William W. Shriver

Registered Professional Engineer Utah Registration no. 8632